


FIG. 1



BEST AVAILABLE COPY

FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10






FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16A




FIG. 16B




FIG. 17




FIG. 18






FIG. 19 A




FIG. 19 B




FIG. 20 A




FIG. 20 B




FIG. 20 C




FIG. 21




FIG. 22




FIG. 23 A




FIG. 23 B




FIG. 23 C





FIG. 24




**FIG. 25** Plus Side Terminal T1

FIG. 26






FIG. 27




FIG. 28




FIG. 29 A




FIG. 29 B




FIG. 30




FIG. 31




FIG. 32




FIG. 33A




FIG. 33B




FIG. 34






FIG. 35




FIG. 36




FIG. 37




FIG. 38




FIG. 39




FIG. 40




FIG. 41




FIG. 42




FIG. 43




FIG. 44 A




FIG. 44 B




FIG. 44 C




FIG. 45




FIG. 46




FIG. 47




FIG. 48




FIG. 49




FIG. 50




FIG. 51




FIG. 52A




FIG. 52B






FIG. 53A




FIG. 53B




FIG. 53C




FIG. 53D




FIG. 54A




FIG. 54B




FIG. 55




FIG. 56




FIG. 57A




FIG. 57B




FIG. 57C




FIG. 57D




FIG. 58




FIG. 59A




FIG. 59B




FIG. 60A




FIG. 60B




FIG. 60C




FIG. 60D





FIG. 60E



**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record.**

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ **BLACK BORDERS**
- ☐ **IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- ☐ **FADED TEXT OR DRAWING**
- ☒ **BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- ☐ **SKEWED/SLANTED IMAGES**
- ☐ **COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- ☐ **GRAY SCALE DOCUMENTS**
- ☐ **LINES OR MARKS ON ORIGINAL DOCUMENT**
- ☐ **REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- ☐ **OTHER:** \_\_\_\_\_

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.**